

Command= 210-Point#, Start#-End# or G#= 1-556Distance Elev Descrip Pnt. Northing Easting Type ----02-10-2025----12:17:35---------D:...\BMHOME16 5000.0000 5000.0000 1 2 5010.9155 4950.8987 TRA 3 5012.7948 4942.4450 TRA 4 5024.0575 4891.7818 TRA 5 5122.0003 4911.9608 TRA 6 5108.5198 4972.6005 TRA 7 5106.3541 4982.3427 SS 8 5097.6043 5021.7018 TRA 9 5065.0834 4954.0917 TRA 10 5061.0352 4972.2663 TRA 11 5086.7540 5070.5103 TRA 12 5065.3006 5167.0145 TRA 13 4967.4273 5146.5008 TRA 14 4989.1496 5048.8085 TRA 15 5080.9212 5170.2885 TRA 5162.6163 16 5190.0044 TRA 17 5219.9410 4932.1394 INT 18 5114.0075 5178.2921 TRA 5199.1401 19 5200.5312 TRA 20 5394.9667 5245.9894 TRA 21 5433.8537 5255.3593 TRA 22 5458.2044 4981.2284 INT 23 5258.1374 4940.0089 INT 24 5497.4007 4989.3040 INT 25 5546.3917 4999.3975 TRA 26 5457.5498 5156.1499 TRA 5480.7811 27 5058.8858 TRA 28 5529.4064 5070.5298 TRA 29 5546.3960 4999.3984 INT 30 5482.4626 5267.0716 TRA 5506.1749 5167.7939 31 INT 32 5441.9262 5049.3814 TRA 33 5430.3105 5098.0134 TRA 34 5074.9235 5333.0127 TRA 35 5344.6284 5026.2915 TRA 36 5393.2773 5037.8364 TRA 37 5409.2091 4971.1340 INT 38 5418.6948 5146.6455 TRA 39 5370.0459 5135.1005 TRA 40 5346.3578 5234.2771 INT 9.39 5106.3541 4982.3427 50 1capj&b TRA 9.76 2setspk 51 4995.4631 4984.3980 TRA 52 5065.4105 5166.7214 fndip SS 53 5097.6485 5021.7219 fndip SS 54 5108.1231 4972.7952 SS fndip 4911.9657 fndip 55 5122.0681 SS

| | and 752 [| | | | | | |
|---------|--------------|---------------|------------------|------------|------------------------|------------------------|------------|
| Bearing | Distance | | Descrip | | | Easting D: | Type |
| | | 02 10 | fndipin | 56 | 5065.1449 | | SS |
| | | | fndipin | 57 | 5061.0623 | 4972.3086 | SS |
| | | | fndip | 58 | 5000.0265 | 4999.9772 | SS |
| | | | corshed corshed | 59 60 | 5081.0821 5089.1434 | 4999.7907 5001.6036 | SS SS |
| | | | corshed | 61 | 5087.4474 | 5009.2186 | SS SS |
| | | | corhse | 62 | 5045.5553 | 4981.9662 | SS |
| | | | cordeck | 63 | 5057.3319 | 4984.5087 | SS |
| | | | cordeck | 64 | 5059.8532 | 4972.7499 | SS |
| | | | corhse corhse | 65 66 | 5058.9430 5061.6418 | 4968.5380 4956.1686 | SS SS |
| | | | corwll | 67 | 4967.9202 | 5145.3788 | SS |
| | | | fndip | 68 | 4991.1122 | 5049.1721 | SS |
| | | | fndip | 69 | 5000.0354 | 4999.9603 | SS |
| | | | fndipin | 70 | 5012.9565 | 4942.5145 | SS |
| | | | fndip fndip | 71 72 | 5010.9452 5024.4689 | 4950.8920 4891.3544 | SS SS |
| | | | corhse | 73 | 5024.4009 | 4949.4083 | SS |
| | | | stoop** | 74 | 5019.6343 | 4961.5511 | SS |
| | | | corhse | 75 | 5017.9799 | 4974.3182 | SS |
| | | 0 40 | . | 76 | 4996.3143 | 4996.2085 | SS |
| | | 8.48 8.92 | tp scstbm23 | 77 78 | 5019.4032 4991.9798 | 4890.3677 4879.4682 | SS SS |
| | | 9.21 | @corhse | 79 | 5023.2010 | 4949.4859 | SS |
| | | 10.06 | stoop** | 80 | 5020.5661 | 4961.6983 | SS |
| | | 9.50 | @corhse | 81 | 5017.7418 | 4974.3013 | SS |
| | | 9.58 | gnd | 82 | 5012.4495 | 4999.6467 | SS |
| | | 12.94 9.60 | bottrm** gnd | 84 | 5011.0651 5002.6808 | 5004.8044 4958.4955 | SS SS |
| | | 9.93 | clrd | 85 | 4988.5956 | 4957.0225 | SS |
| | | 9.41 | gnd | 86 | 5005.9670 | 4944.5568 | SS |
| | | 8.98 | gnd | 87 | 5038.0994 | 4949.9639 | SS |
| | | 11.53 | bottrm** | | 5034.1835 | 4907.6229 | SS |
| | | 9.40 | deck** gnd | 89 90 | 5045.4811 5050.9212 | 4982.6082 5008.1745 | SS SS |
| | | 9.97 | gnd | 91 | 5064.0777 | 5010.8866 | SS |
| | | 9.81 | gnd | 92 | 5098.0406 | 5020.2126 | SS |
| | | 9.17 | gnd | 93 | 5079.8287 | 4998.5843 | SS |
| | | 8.99 7.65 | gnd setpk | 94 95 | 5086.0427 5032.4381 | 4982.0491 4956.2687 | SS SS |
| | | 7.61 | setpk setpk | 96 | 5028.0359 | 4973.7330 | SS |
| | | 7.60 | setpk | 97 | 5023.0386 | 4996.2001 | SS |
| | | 7.60 | setpk | 98 | 5074.8953 | 4984.1376 | SS |
| | | | corfnd | 101 | 5023.0479 | 4996.1814 | |
| | | | corfnd corfnd | 102 103 | 5028.0399 5069.9037 | 4973.7297 5006.5995 | |
| | | | corfnd | 104 | 5074.8957 | 4984.1478 | |
| | | | corfnd | 105 | 5048.0512 | 4978.1791 | |
| | | | corfnd | 106 | 5051.9580 | 4960.6082 | |
| | | | corfnd | 107 108 | 5032.4348 | 4956.2673 | |
| | | | corfnd | 108 | 5028.5280 5006.9106 | 4973.8382 4969.0296 | INT |
| | | | | 150 | 5021.1482 | 5004.7022 | INT |
| | | | | 151 | 5001.8899 | 4991.4986 | INT |
| | | | | 152 | 5001.9121 | 4991.5006 | INT |
| | | | | 153 154 | 5006.8846 5034.4431 | 4969.0310 4947.2669 | INT INT |
| | | | | 154 | 5034.4431 | 4947.2669 | INT |
| | | | | 100 | 3031.1303 | 1511.5051 | T 1 4 T |

pole

pole

corhse

corhse

flagpole 312

308

309

310

311

5402.9070

5395.7533

5406.0006

5416.8714

5350.0860

5243.9795

5237.3182

5194.7972

5182.6281

5234.4407

SS


SS

SS

SS

SS

Google Maps



Map data ©2016 Google 20 ft

1 of 1 7/5/2016 8:55 PM

809 OCEAN BLVD

Location 809 OCEAN BLVD **Mblu** 197/ 37/ / 1/

Acct# 4719 Owner SMITH, MARY V.

Assessment \$835,400 **Appraisal** \$835,400

PID 4719 Building Count 2

Current Value

| Appraisal | | | | | |
|----------------|--------------|-----------|-----------|--|--|
| Valuation Year | Improvements | Land | Total | | |
| 2016 | \$308,700 | \$526,700 | \$835,400 | | |
| | Assessment | | | | |
| Valuation Year | Improvements | Land | Total | | |
| 2016 | \$308,700 | \$526,700 | \$835,400 | | |

Owner of Record

Owner SMITH, MARY V. Sale Price \$0

Co-Owner Certificate

 Address
 809 OCEAN BLVD.
 Book & Page
 2570/0755

HAMPTON,, NH 03842-4308 Sale Date 10/29/1985

Ownership History

| Ownership History | | | | |
|-------------------|------------|-------------|-------------|------------|
| Owner | Sale Price | Certificate | Book & Page | Sale Date |
| SMITH, MARY V. | \$0 | | 2570/0755 | 10/29/1985 |

Building Information

Building 1: Section 1

 Year Built:
 1913

 Living Area:
 2,042

 Replacement Cost:
 \$274,395

Building Percent

70

Good:

Replacement Cost

Less Depreciation: \$192,100


| Building Attributes | | | | |
|---------------------|----------------|--|--|--|
| Field | Description | | | |
| Style | Conventional | | | |
| Model | Residential | | | |
| Grade: | Average +10 | | | |
| Stories: | 2 Stories | | | |
| Occupancy | 1 | | | |
| Exterior Wall 1 | Vinyl Siding | | | |
| Exterior Wall 2 | | | | |
| Roof Structure: | Gable/Hip | | | |
| Roof Cover | Asph/F Gls/Cmp | | | |
| Interior Wall 1 | Plastered | | | |
| Interior Wall 2 | | | | |
| Interior Flr 1 | Pine/Soft Wood | | | |
| Interior Flr 2 | | | | |
| Heat Fuel | Gas | | | |
| Heat Type: | Hot Water | | | |
| AC Type: | None | | | |
| Total Bedrooms: | 4 Bedrooms | | | |
| Total Bthrms: | 1 | | | |
| Total Half Baths: | 1 | | | |
| Total Xtra Fixtrs: | | | | |
| Total Rooms: | 7 | | | |
| Bath Style: | Modern | | | |
| Kitchen Style: | Formica-M cab. | | | |
| МНР | | | | |

Building Photo



(http://images.vgsi.com/photos/HamptonNHPhotos// $00\00\47/38.jpg$)

Building Layout



| | Building Sub-Areas (sq ft) <u>L</u> | | | |
|------|-------------------------------------|---------------|----------------|--|
| Code | Description | Gross Area | Living Area | |
| FUS | Upper Story, Finished | 1,040 | 1,040 | |
| BAS | First Floor | 1,002 | 1,002 | |
| CRL | Crawl Space | 40 | 0 | |
| FEP | Porch, Enclosed, Framed | 320 | 0 | |
| PTO | Patio | 36 | 0 | |
| UBM | Basement, Unfinished | 1,160 | 0 | |
| WDK | Deck, Wood | 431 | 0 | |
| | | 4,029 | 2,042 | |

Building 2: Section 1

Year Built:1945Living Area:1,673Replacement Cost:\$154,098

Building Percent 75

Good:

Replacement Cost

Less Depreciation: \$115,600


| Building Attributes: Bldg 2 of 2 | | | |
|----------------------------------|---------------------|--|--|
| Field | Description | | |
| Style | 2 Family Conversion | | |
| Model | Residential | | |
| Grade: | Average | | |
| Stories: | 2 Stories | | |
| Occupancy | 2 | | |
| Exterior Wall 1 | Vinyl Siding | | |
| Exterior Wall 2 | Wood Shingle | | |
| Roof Structure: | Gable/Hip | | |
| Roof Cover | Asph/F Gls/Cmp | | |
| Interior Wall 1 | Plywood Panel | | |
| Interior Wall 2 | K PINE/A WD | | |
| Interior Flr 1 | Pine/Soft Wood | | |
| Interior Flr 2 | | | |
| Heat Fuel | Gas | | |
| Heat Type: | Floor/Wall Htr | | |
| AC Type: | None | | |
| Total Bedrooms: | 4 Bedrooms | | |
| Total Bthrms: | 2 | | |
| Total Half Baths: | 0 | | |
| Total Xtra Fixtrs: | | | |
| Total Rooms: | 8 | | |
| Bath Style: | Modern | | |
| Kitchen Style: | Formica-S cab. | | |
| MHP | | | |

Building Photo



(http://images.vgsi.com/photos/HamptonNHPhotos//\00\00 \47/39.jpg)

Building Layout



| | Legend | | |
|------|-----------------------|---------------|----------------|
| Code | Description | Gross Area | Living Area |
| BAS | First Floor | 859 | 859 |
| FUS | Upper Story, Finished | 814 | 814 |
| CRL | Crawl Space | 648 | 0 |
| SLB | Con. Slab | 166 | 0 |
| WDK | Deck, Wood | 64 | 0 |
| _ | | 2,551 | 1,673 |

Extra Features

| Extra Features <u>Legen</u> | | | | |
|-----------------------------|-------------|---------|---------|--------|
| Code | Description | Size | Value | Bldg # |
| HRT | HEARTH | 1 UNITS | \$1,000 | 1 |

Land

| Land Use | | Land Line Valuation | |
|---------------|-------------------|---------------------|-----------|
| Use Code | 1090 | Size (Acres) | 0.12 |
| Description | MULTI HSES MDL-01 | Frontage | 0 |
| Zone | RA | Depth | 0 |
| Neighborhood | 90 | Assessed Value | \$526,700 |
| Alt Land Appr | No | Appraised Value | \$526,700 |
| Category | | | |

Outbuildings


| Outbuildings | <u>Legend</u> |
|--------------------------|---------------|
| No Data for Outbuildings | |


Valuation History

| Appraisal | | | | | |
|----------------|--------------|-----------|-----------|--|--|
| Valuation Year | Improvements | Land | Total | | |
| 2015 | \$250,800 | \$458,100 | \$708,900 | | |
| 2014 | \$250,800 | \$458,100 | \$708,900 | | |
| 2013 | \$250,800 | \$458,100 | \$708,900 | | |

| Assessment | | | | | |
|----------------|--------------|-----------|-----------|--|--|
| Valuation Year | Improvements | Land | Total | | |
| 2015 | \$250,800 | \$458,100 | \$708,900 | | |
| 2014 | \$250,800 | \$458,100 | \$708,900 | | |
| 2013 | \$250,800 | \$458,100 | \$708,900 | | |

(c) 2016 Vision Government Solutions, Inc. All rights reserved.





Jed Mary Sold BM JOB 16 (NCLUBES PRICES VENERAL PRICES POR PRICES PRINCES PRIN SW 8/10/16

| | Command= 8- Angle Right Output Command= 10- | | | | | | |
|-------------|--|----------------------|------------------|------------|------------------------|------------------------|------------------|
| | Bearing | Distance 08-10 | Descrip | Pnt. | Northing: 30 | Easting | Type BMHOME16 |
| | Occupied Point= 300 | | | | | | |
| | Backsight Point= 301 | | 1sethub | 300 | 5432.5865 | 5253.7936 | OCC |
| | 94-46-46 | 204.57 | 2sethub | 301 | 5449.6313 | 5049.9349 | BS |
| | Storage Point= 82- | | 1sethub | 300 | 5432.5865 | 5253.7936 | OCC AZ |
| | Point= 363 354-20-57 | 155.87 P | | | | | |
| | 45 | 11 V | final 1sethub | 363 300 | 5430.2158 5432.5865 | 5097.9461 5253.7936 | INV AR |
| | Point= 364 347-45-41 | | ok and | | -500K | | |
| | (. 347-45-20 108, | -20 108,1350 | final 1sethub | 364 300 | 5418.5474 5432.5865 | 5146.5655 5253.7936 | INV AR |
| | Point= 361 277-01-45 | loch | 00 | 6-55 0 | | | |
| | | 38.69 03-00 Set C | final 1sethub | 361 300 | 5394.7134 5432.5865 | 5245.8755 | INV AR |
| | Point= 301 | | | 300 | 5432.5865 | 5253.7936 | |
| | 00-00-00 204.57 | 2sethub | 301 | 5449.6313 | 5049.9349 | INV AR | |
| | Point= 306 | 1sethub | 300 | 5432.5865 | 5253.7936 | | |
| | 278-05-50 | 88.68 | | | | 5024 0210 | |
| | | | fndip 1sethub | 306 | 5346.1366 5432.5865 | 5234.0310 5253.7936 | INV AR |
| | Point= 121- Saving Job disk C: is 32% full. 215820767232 Bytes free on disk. | | | | | | |
| Command= 4- | | | | | | | |

No Vanianies Int 1.3 granted SHE WENT IN HOSPITALS 2206-541 2183-140 1766-025



Tocky Bialobrzeski <tockybialo@gmail.com>

(no subject)

1 message

Tocky B <tockybialo@gmail.com>
To: Tocky <tockybialo@gmail.com>

Sat, Jun 18, 2016 at 12:24 PM

Tocky here. You are sick, I am in pain. We need to stop and take care of ourselves. I will offer an estimate of \$2000-\$2500 to prepare the necessary condominium site and floor plans for Peter Saari to use for planning board submittal and to draw up your declarations. We will have to talk about the timing of this work when we can both function again. Please get well and I will wait to hear from you when you are feeling better.

Send This as a text le |z | 16 te

to have

surgery.

125-125 S

HAI

Atty, Allison said it is not a feasible situation,

Mr. Ring felt the first concern was fire safety, They are blocking access to the building in the rear,

Mr. True said he sees alternatives, and Mr. Lonergan and Mrs. Williams agreed.

Wendell Ring MCVED to deny the petition as it is not in the spirit and intent of the ordinance to put things in the settlecks, it is against the public interest as it would be detrimental to fire protection and no hardship has been proven.

VOTE: 5 in favor to deny the petition. (Unanimous)

ITICH NOT GRANTED

87

Mary Virginia Smith - 809 Ocean Blyd.

The Clerk read the petition into the record. Mary Virginia Smith was present. She is requesting a variance from Art. 1.3, expansion of a non-conforming use to allow the construction of a 10' x 11' deck on the south side of the front dwelling.

Miss Smith said she had a building permit for windows which are being worked on now. There is an existing deck on the back of her house. The new deck will not go out any further than the existing house.

Dr. Stonie clarified that the deck entered from a porch.

Joseph Hurley, 807 Ocean Blvd., spoke in favor of the petition, he felt he would be the only one to see it.

Faul Cowan, 813 Ocean Blvd., also spoke in favor of the petition.

Leal Gadwah asked the location of the stairs, and Ms. Smith explained that they will go on the south.

Kevin Lonergan MOVED to approve the petition.

Mendell Ring SECONDED

YOTE: 5 in favor to grant the petition (Unanimous)

MON GRANTED

Fishard and Beatrice Violette - 185 King's Highway

The Clerk read the petition into the record. Richard and Beatrice Violette were present.

